

Date:	2022.11.23
Aircraft Firmware:	v01.00.5200
Phantom 4 Pro V2.0 Remote Controller Firmware:	v01.00.60.10
Phantom 4 Pro+ V2.0 Remote Controller Firmware:	v0.4.8.2
DJI GO 4 App iOS:	v4.3.54
DJI GO 4 App Android:	v4.3.54

What's New?

• Fixed some known issues.

- Restart the aircraft and remote controller once the update is complete.
- The update may reset various flight parameters such as the RTH altitude and the maximum flight distance. Before updating, take note of your preferred settings and readjust them in DJI GO 4 after the update.
- If the firmware update fails, restart the aircraft, remote controller and DJI GO 4 app or DJI Assistant 2, then try updating again.



Date:	2020.08.03
Aircraft Firmware:	v01.00.52.00
Phantom 4 Pro V2.0 Remote Controller Firmware:	v01.00.52.00
Phantom 4 Pro+ V2.0 Remote Controller Firmware:	v01.00.04.00
DJI GO 4 App iOS:	v4.3.37
DJI GO 4 App Android:	v4.3.36

What's New?

- Optimized IQ parameter of camera to improve camera image quality.
- Increased the maximum transmission distance: 10 km (FCC), 6 km (CE/MIC/SRRC).

Notes:

• If the firmware update fails, restart the aircraft, remote controller, and DJI GO 4 app, and try updating again.



Date:	2019.12.25
Aircraft Firmware:	v01.00.50.00
Phantom 4 Pro V2.0 Remote Controller Firmware:	v01.00.50.00
Phantom 4 Pro+ V2.0 Remote Controller Firmware:	v01.00.04.00
DJI GO 4 App iOS:	v4.3.29
DJI GO 4 App Android:	v4.3.25

What's New?

- Optimized flight controller parameters to improve flight experience.
- Optimized sensitivity of the shutter button of the remote controller to improve shooting experience.
- Optimized IQ and AWB parameters of camera to improve camera image quality.
- Fixed some issues.

- Once the firmware is updated, it cannot revert to a previous version. Restart the aircraft and remote controller once the update is complete.
- If the firmware update fails, restart the aircraft, remote controller, and DJI GO 4 app, and try updating again.



Date:	2018.10.24
Aircraft Firmware:	v01.00.22.00
Phantom 4 Pro V2.0 Remote Controller Firmware:	v01.00.22.00
Phantom 4 Pro+ V2.0 Remote Controller Firmware:	v01.00.01.00
DJI GO 4 App iOS:	v4.3.3
DJI GO 4 App Android:	v4.3.2

What's New?

- Optimized the sensitivity of the remote controller's right stick when adjusting camera parameters.
- Fixed an issue where after restarting, the remote controller automatically reset to Mode 2 even if the remote controller was set in a different mode.

- Once the firmware is updated, it cannot revert to a previous version. Restart the aircraft and remote controller once the update is complete.
- If the firmware update fails, restart the aircraft, remote controller, and DJI GO 4 app, and try updating again.



2018.10.08
v01.00.20.00
v01.00.20.00
v01.00.01.00
v4.3.2
v4.3.0

What's New?

- Added support for Ground Station Pro (GS Pro).
- Updated the video transmission system to OcuSync 2.0.
- Added support to connect two DJI Goggles through Multiuser Mode (Currently only available on iOS and requires DJI GO 4 v4.3.2 or above).
- Fixed an issue when moving the remote controller control sticks in Gain & Expo Tuning where the EXP value moved erratically.

- When using the Phantom 4 Pro/Pro+ V2.0 with GS Pro, connect the remote controller to the PC before powering on the remote controller and the aircraft.
- Once the firmware is updated, it cannot revert to a previous version. Restart the aircraft and remote controller once the update is complete.
- If the firmware update fails, restart the aircraft, remote controller, and DJI GO 4 app, and try updating again.



Date:	2018.06.26
Aircraft Firmware:	v01.00.15.00
Phantom 4 Pro V2.0 Remote Controller Firmware:	v01.00.15.00
Phantom 4 Pro+ V2.0 Remote Controller Firmware:	v01.00.01.00
DJI GO 4 App iOS:	v4.2.20
DJI GO 4 App Android:	v4.2.20

What's New?

- Optimized compass calibration.
- Optimized gimbal performance to improve its stability during flight.

- Once the firmware has been updated, it cannot be reverted to a previous version. Restart the aircraft and remote controller once the update is complete.
- If the firmware update fails, restart the aircraft, remote controller, and DJI GO 4 app/DJI Assistant 2, then try updating again.